

Note: Some lithologic units may have been combined for presentation in this figure and the lithologic description may not correspond exactly to the description in the lithologic log shown in table.

Figure 4*E*. Geophysical logs, lithology, and well construction for Riverview (1S/3W-15K1-5) multiple-depth monitoring well site, San Bernardino area, southern California.